














# ODA-8800









1/4

A1  X2	A2 MANUAL  X1	A3  X2	A4  X2	A5  X1	A6  X2
---	---	---	---	---	---
























2/4

A8  X1	A9  X1	A7  X4
---	---	---

3/4

A10  X1	A11  X1	A12  X2	A13  X1
--	--	--	---

4/4

A14  X1	A15  X1	A16  X2	A18  X1	A19  X1	A20  X1	
A21  X1	A22  X1	A23  X2	A24  X2	A25  X4	A26  X4	A27  X8
A28  X4	A29  ST4X50=8 ST4X12=38 ST4X35=2	A30  Ø2.8 X1	A31  M4X25=2 X2	A32  ST4X12=4 X4	A33  X1	A34  X1
A35  X1	A36  X1	A37  X2	<h1>1</h1>			

